


STATE PROCUREMENT OFFICE EMERGENCY PROCUREMENT

16 MAY -5 A9:23



Chief Procurement Officer					
: Department of Defense, HIENG					
Name of Requesting Department			_		
Pursuant to HRS § 103D-307 and HAR chapter 3-122, Subchapter 10, the Department requests approval for the following:					
d of Emergency: 01-022 FEB 2016	2. After-th	ne-Fact:	☑ Yes □ No		
3. Describe in detail the emergency situation that created a threat to life, public health, welfare or safety. Due to corrosion caused by the contact of dissimilar metals, a hose bibb fitting separated from the supply line in an interior mechanical room of Building 710 at the Regional Training Institute at Waimanalo. This subjected the full volume of water from the supply line into the mechanical room, and building. This occurred sometime after the occupants vacated the building on Friday (1/29/16) afternoon, and was not discovered until Monday (2/1/16) morning. Five classrooms, two large office spaces, and three major hallways sustained water damage.					
ractor/Service Provider Name: Pamcov, Inc. du diol 20 Property pedioration Cernices	lv	5. Amount o \$ 41,76	-		
6. Describe in detail the emergency goods, services, or construction and explain why it is necessary. To prevent the spread of water (and further water damage) and mold growth, a water remediation company was immediately called in. Industry guidelines state that mold begins to grow within 24-48 hours in conditions similar to that encountered. The standing water was immediately removed, and dehumidifiers and fans placed in the affected spaces. Lessons learned from a prior flooding incident guided us to immediately start drying the walls from the inside. This was accomplished by drilling holes in the affected walls, and inserting air tubes into the wall cavity.					
7. State the reason(s) the vendor/contractor/service provider was selected. Explain what competition, as is practicable, was conducted. The vendor selection was made from a quick online survey of available water remediation contractors. A different contractor was selected from the one recently utilized for the Building 306 (Ft Ruger) flooding occurrence. Due to the short time before mold starts to grow, and the need to isolate the water damage to as small an area as possible, once confirmation of availability was obtained from this contractor, no other companies were called.					
	Department of Defense, HIENG Name of Requesting Department 10 103D-307 and HAR chapter 3-122, Subchapter 10, the Department 11 of Emergency: 01-022 FEB 2016 12 etail the emergency situation that created a threat to life, procured to the contact of dissimilar metals, a hose bibb fit in of Building 710 at the Regional Training Institute at Wailine into the mechanical room, and building. This occurred ay (1/29/16) afternoon, and was not discovered until Moles, and three major hallways sustained water damage. 12 Property Perforation Cernice: 13 etail the emergency goods, services, or construction and expread of water (and further water damage) and mold grow the standing water was immediately removed, and dehumic from a prior flooding incident guided us to immediately syndrilling holes in the affected walls, and inserting air tuber of the context of the vendor/contractor/service provider was selected from the one recently utilized for the Building 30 of distarts to grow, and the need to isolate the water damage	Department of Defense, HIENG Name of Requesting Department 3 103D-307 and HAR chapter 3-122, Subchapter 10, the Department requests d of Emergency: 01-022 FEB 2016 2. After-the etail the emergency situation that created a threat to life, public heal in caused by the contact of dissimilar metals, a hose bibb fitting separm of Building 710 at the Regional Training Institute at Waimanalo. The line into the mechanical room, and building. This occurred sometima ay (1/29/16) afternoon, and was not discovered until Monday (2/1), es, and three major hallways sustained water damage. Property Pedoration Certices etail the emergency goods, services, or construction and explain why pread of water (and further water damage) and mold growth, a wateled in. Industry guidelines state that mold begins to grow within 24-4 e standing water was immediately removed, and dehumidifiers and from a prior flooding incident guided us to immediately start drying a drilling holes in the affected walls, and inserting air tubes into the value of the value of the value of the suiding 306 (Ft Ruger distarts to grow, and the need to isolate the water damage to as small distarts to grow, and the need to isolate the water damage to as small distarts to grow, and the need to isolate the water damage to as small distarts to grow, and the need to isolate the water damage to as small distarts to grow, and the need to isolate the water damage to as small distarts to grow, and the need to isolate the water damage to as small distarts to grow, and the need to isolate the water damage to as small distarts to grow, and the need to isolate the water damage to as small distarts to grow.	Department of Defense, HIENG Name of Requesting Department \$103D-307 and HAR chapter 3-122, Subchapter 10, the Department requests approval for the dof Emergency: 01-022 FEB 2016 2. After-the-Fact: 10 etail the emergency situation that created a threat to life, public health, welfare or a caused by the contact of dissimilar metals, a hose bibb fitting separated from the mof Building 710 at the Regional Training Institute at Waimanalo. This subjected line into the mechanical room, and building. This occurred sometime after the oct and (1/29/16) afternoon, and was not discovered until Monday (2/1/16) morning es, and three major hallways sustained water damage. Fractor/Service Provider Name: Pamcov, the discovered until Monday (2/1/16) morning es, and three major hallways sustained water damage. 5. Amount of \$41,70 etail the emergency goods, services, or construction and explain why it is necessal pread of water (and further water damage) and mold growth, a water remediationed in. Industry guidelines state that mold begins to grow within 24-48 hours in content of the standing water was immediately removed, and dehumidifiers and fans placed in from a prior flooding incident guided us to immediately start drying the walls frow drilling holes in the affected walls, and inserting air tubes into the wall cavity. Fron(s) the vendor/contractor/service provider was selected. Explain what competition was made from a quick online survey of available water remediation contracted the starts to grow, and the need to isolate the water damage to as small an area as presented as the starts to grow, and the need to isolate the water damage to as small an area as presented the starts to grow, and the need to isolate the water damage to as small an area as presented to the starts to grow, and the need to isolate the water damage to as small an area as presented to the starts to grow, and the need to isolate the water damage to as small an area as presented to the starts to grow, and the need to isolate the water damage to as		

8. Identify the primary responsible staff person(s) conducting and managing this procurement. (Appropriate delegated procurement authority and completion of mandatory training required.) *Point of contact (Place asterisk after name of person to contact for additional information.)					
Name	Division/Agency	Phone Number	E-mail Address		
Glenn S. Matsuda	HIENG	(808) 672-1540	glenn.s.matsuda@hawaii.gov		
All requirements/approvals and internal controls for this expenditure is the responsibility of the department. I certify that the information provided is to the best of my knowledge, true and correct. 4.26.16 Department Head Signature Date					
For Chief Procurement Officer Use Only Chief Procurement Officer (CPO) Comments:					
Approval is granted based on the department's determination that water damage to five classrooms, two large office spaces, and three major hallways at the Regional Training Institute at Waimanalo required immediate action as it created a threat to the public's health and safety. Pursuant to HRS \$103D-310(c) and HAR \$3-122-112, the procuring officer shall verify compliance (i.e. vendor is required to provide proof of compliance and may use the Hawaii Compliance Express) and the award is required to be posted on the Awards Reporting System. Copies of compliance and the award posting are required to be documented in the procurement/contract file.					
If there are any questions, please	contact Stacey Kauleinamo	ku at 586-0571, or stacey.l.kaul	einamoku@hawaii.gov.		
☑ Approved □ Dis		ion Required Frequence of Recover and the Common C	S (16 (16 Date		